

1A



DTC P0353 (C26)

DTC Detecting Condition and Trouble Area

DTC detecting condition	Trouble area
P0353 (C26): Ignition System #1 (Side) Malfunction Ignition coil #1 (side) signal is interrupted by 4 times or more continuity although CKP signal is detected.	Refer to No Spark or Poor Spark .