

1A



## DTC P0507 (C65)

### DTC Detecting Condition and Trouble Area

| DTC detecting condition  | Trouble area  |
|--|---|
| <b>P0507 (C65): ISC Valve, Higher Than Desired RPM</b><br>Idle speed rose higher than desired idle speed by more than specified range. | <ul style="list-style-type: none"><li>• Air passage</li><li>• STVA</li><li>• Engine mechanism</li></ul> |

### Troubleshooting

**NOTICE:**

Be careful not to disconnect the STVA coupler at least 5 seconds after ignition switch is turned to OFF.

If the ECM coupler is disconnected within 5 seconds after ignition switch is turned to OFF, there is a possibility of an unusual value being written in the ECM and causing an error of ISC valve operation.

Refer to [DTC P0506 \(C65\)](#).