

2C



Rear Suspension On-vehicle Inspection

Inspect the rear shock absorber (1) for oil leakage and check that there is no play in the swingarm (2).

Replace any defective parts, if necessary.

- Rear shock absorber replace:
- Swingarm pivot shaft and bearing inspection:
- Cushion lever inspection:
- Cushion rod inspection:
- Swingarm inspection:

