

1A



DTC P0351 (C24)

DTC Detecting Condition and Trouble Area

DTC detecting condition	Trouble area
P0351 (C24): Ignition System #1 (Center) Malfunction Ignition coil #1 (center) signal is interrupted by 4 times or more continuity although CKP signal is detected.	Refer to No Spark or Poor Spark .