

1A



## DTC P0352 (C25)

### DTC Detecting Condition and Trouble Area

DTC detecting condition	Trouble area
<b>P0352 (C25): Ignition System #2 (Center) Malfunction</b> Ignition coil #2 (center) signal is interrupted by 4 times or more continuity although CKP signal is detected.	Refer to <a href="#">No Spark or Poor Spark</a> .