

1A



DTC P0354 (C27)

DTC Detecting Condition and Trouble Area

DTC detecting condition	Trouble area
P0354 (C27): Ignition System #2 (Side) Malfunction Ignition coil #2 (side) signal is interrupted by 4 times or more continuity although CKP signal is detected.	Refer to No Spark or Poor Spark .