

9B



Rear Combination Light Replacement

NOTE:

If LED operation is abnormal, replace the rear combination light with a new one.